


























## 1.4.2 Geberit UP-Spülkästen mit Betätigung von vorne / von oben ab Baujahr 1978

14

■ GEBERIT

		 <p>ab 1974 ab 1981 ab 1980 ab 1995</p>	 <p>ab 1988 ab 1995</p>			
		PA I/IX 2761/I	PA I/IX 2761/I	PA I/IX 2761/I	PA I/IX 3403/I PA I/IX 3495/I PA I/IX 3535	PA I/IX 3403/I PA I/IX 3495/I PA I/IX 3535
		10.800 (Schutzplatte transparent, Befestigungsschrauben aus Messing) (1978–1987)	110.855/857 110.900 (Schutzplatte weiß) (1988–1997)	110.857/900 110.133 (1998–2004)	110.962/963 (1986–1994)	110.970/975 (ab 1995)
	Service Umbau-Set (Wassersparset)	240.835.00.1 & Betätigungsplatte Twinline	240.515.00.2 & Betätigungsplatte Twinline	–	–	–
	Ersatzheberglocke (Spülgarnitur)	240.114.00.1	240.114.00.1	240.501.00.1	240.114.00.1	240.113.00.1
	Bügelset für Heberglocke	241.167.00.1	241.167.00.1	241.167.00.1	241.167.00.1	241.167.00.1
	Heberglockendichtung	816.418.00.1 (Ø 63x32)	816.418.00.1 (Ø 63x32)	816.418.00.1 (Ø 63x32)	816.418.00.1 (Ø 63x32)	816.418.00.1 (Ø 63x32)
	Füllventil Impuls380	240.705.00.1	240.705.00.1	240.705.00.1	240.705.00.1 + 240.321.00.1 <sup>1</sup>	240.705.00.1
	Dichtungsset zu Füllventil Unifill	240.771.00.1	240.771.00.1	240.771.00.1	240.771.00.1	240.771.00.1

	1. Verbindungsschlauch 2. Dichtungsset	–	240.069.00.1 (1.) 240.922.00.1 (2.)	240.069.00.1 (1.) 240.922.00.1 (2.)	240.321.00.1 (1.)	240.321.00.1 (1.)
	O-Ring zu Steckverbindung ø 45	362.771.00.1	362.771.00.1	362.771.00.1	362.771.00.1	362.771.00.1
	Eckventil	216.599.00.1	216.599.00.1	216.599.00.1	216.599.00.1	216.599.00.1
	Bassin (Austausch)	240.195.00.1	240.195.00.1	240.500.00.1	240.195.00.1	240.195.00.1
	Bassinichtung	240.282.00.1	240.282.00.1	240.282.00.1	240.282.00.1	240.282.00.1
	Niederhalter	241.170.00.1	241.170.00.1	240.506.00.1	240.072.00.1	240.072.00.1
	Schutzplatte	240.026.00.1	240.073.00.1	240.512.00.1	–	–
	Lagerbock	–	240.510.00.1	240.510.00.1	–	–
	Betätigungsplatten	115.222.xx.1 115.888.xx.1	115.222.xx.1 115.888.xx.1	115.222.xx.1 115.888.xx.1	115.333.xx.1	115.333.xx.1
	Umrüstsets auf neue Betäti- gungsplatte	–	–	–	240.175.00.1 240.178.00.1	240.175.00.1 240.178.00.1
	Verlängerungsset (bei erhöhter Vor-/Aufmaue- rung)	–	240.058.00.1	240.058.00.1	240.087.00.1 240.178.00.1	240.180.00.1
	1. Drückerstange 2. Distanzbolzen	216.024.00.1 (messing)	240.074.00.1 (1.) 240.067.00.1 (2.)	240.074.00.1 (1.) 240.067.00.1 (2.)	–	240.323.00.1 (1.)
	Bauschutz	240.233.00.1	240.233.00.1	240.233.00.1	–	–
	<b>Staeinsatz</b>	217.807.00.1	217.807.00.1	217.807.00.1 <b>240.476.00.1</b> <b>(ab 1997)</b>	<b>240.476.00.1</b>	<b>240.476.00.1</b>

1. Beim Austausch Kompakt gegen Unifill wird der Verbindungsschlauch 240.321.00.1 zusätzlich benötigt.